x299 pro/se freeze in Monterey or Ventura

Beitrag von „startergo" vom 29. November 2022, 01:43

`SMBS._ADR -> XSBU.XADR`

> Zitat
>
> X299 system don't like this patch. (npci=0x2000(3000)
> I remove this and patched my system with
> SMBS._ADR -> XSBU.XADR

Probably not needed

`Rename _DSM to XDSM (NVDIMM).` This might not be needed, but look here:

> Zitat
>
> Renaming all _DSM to XDSM insures no existing _DSM at the NVMe SSD path. The
> _DSM injection via SSDT_NVMe-Pcc.aml will not work if there is an existing _DSM at
> that path.

Probably not needed.

`Rename HEC1 to IMEI (PAVP)` and `Rename IDER to MEID (PAVP)` as per Apple's naming
convention.

`HPET _CRS to XCRS Rename`, `RTC IRQ 8 Patch`, `TMR IRQ 0 Patch` are generated by [SSDTTime](#)

`Fix RTC Range` is [from](#) [khronokernel](#)

I have updated the config removing some renames in GitHub.

Unfortunately I got the freeze again after a few hours of inactivity with the current setup. What
gives?