`Erledigt` Does Oz understand Xeon CPU's and how to make it work?

Beitrag von „firefly_can_fly" vom 11. Mai 2018, 18:27

> [Zitat von griven](#)
>
> Okay. About your [Bios Settings](#) please make sure that CSM Mode is active for the moment also make sure Secure Boot is disabled. The black Screen issue normally is an issue when the Bios and/or OZ fails to initialize the selected primary GPU. Also disable any FastBoot settings in Bios as well.

From what i did:
1) rechecked bios setting, toggled on CSM mode On. Here are screens on what my bios setting are now:

2) I cant make it work because even after NVRAM flush I have blinking color screens, reboot, and freeze. Shell is not booting, nothing related to OZ not working.
Here is the video of how it looks:
https://drive.google.com/file/d/1DXOqrx_Jmf4abYYbtsUF1aB5U8MZA-IV/view?usp=drive_web

It's definitely not motherboard or hardware components, because I switched motherboard already.
Maybe someone had same problems?