Can not boot after copy EFI to disk

Beitrag von „damquangvinh595“ vom 11. September 2021, 21:40

Hi everyone,

I installed MacOS Bigsur on my laptop. But after copy efi to disk, i can’t boot and stop here (photo). Please help me fix this error.

Thank you!!!

My specs:

HP Spectre X360(8 gen core)

- Processor & Memory: Intel, Core i5 , Core i5-8265U, 3.90 GHz, 8 GB RAM
- Operating System and Software Included:Windows 10 Pro Operating System, Microsoft Office 365, Windows 10 Pro Included
- Storage: Flash Memory Solid State , 256.0 SSD
- Display: 13.3 inches, LED display, 1920 x 1080 (Full HD)
- Ports & Connectivity: 1 USB 3.0 Ports, 0 USB 2.0 Ports, Bluetooth
- General Information: Integrated Graphics Type,Intel UHD Graphics 620