DELL M8400 Sound - welche kext ?

Beitrag von „MacPeet“ vom 6. Mai 2022, 15:45

Ok, mein Screenshot oben war noch vom alten Sourcecode, hatte nicht gesehen, dass es inzwischen weitere Infos dazu gibt.

Er schreibt ja auf seiner Seite, dass er für's Audio bislang speziell was Patchen musste, aber er schreibt auch weiter, dass es mit AppleALC Release 1.7.1 eine Änderung gab auf ID 59 und man diese nun so verwenden kann.

Zitat: "Unterstützung für AppleALC für Dell Precision M4800 (Layout-ID 59) wurde ab Version 1.7.1 mit acidanthera/AppleALC zusammengeführt. Sie können den Treiber in Zukunft von acidanthera/AppleALC aktualisieren."

1.7.1 Latest

v1.7.1

- Fixed EAPD for layout 28 ALC269 by **@samcabral**
- Fixed wrong file name in ALC287 info.plist
- Added dump for ALC225 layout 30 by **@usr-sse2**
- Added Lenovo M920x for ALC235 LayoutID=72 by **@meloay**
- Fixed ALC298 layout-id 11 for Alienware 17 R4 2.1ch by @Rockjesus.cn
- Fixed MSI MPG Z490 Gaming Plus Sound issue after booting from Windows by **@JanoMorano**
- Added NUC8i5BEH JUST MIC layout-id 88 by **@frozenzero123**
- Added layoutid 59 ALC292 for Dell M4800 with dockstation support by **@hansyao**

NOTE: The binary releases published on 18th April did not contain `Added layoutid 59 ALC292 for Dell M4800 with dockstation support by @hansyao`. This has been fixed now. Sorry for the inconvenience.

Bedeutet für Dich, neuste Lilu und AppleALC verwenden und alcid=59 in den Bootargs versuchen.