NVMe Probleme in Big Sur

Beitrag von „MPC561" vom 12. Februar 2024, 18:26

Hi,

Don´t know why you not see the Lexar. But the EFi itself is ... (I try to be polite) "overloaded". I know a notebook need more drivers but 34 drivers in the EFI?

And in addition 32 kexts?

Some of the drivers have a call order.

I beg your pardon but me will surely not clean this EFI.

You should start with this EFI. Only 3 drivers and only necessary Kexts. When MacOS boots and sees the NVME and you installed it you can add additional drivers as open canopy for the graphical boot loader etc.

[Klick Me on Github](#)

But at the end it is possible that you will not be able in general to install MacOS on that HP.

I´m out.