

Anleitung: macOS Sierra auf einem Kaby Lake/Skylake installieren

Beitrag von „Plebejer“ vom 20. Oktober 2016, 09:37

Im BIOS ist die interne Grafik deaktiviert und als initial Display ist auf dem richtigen PCIe aktiviert.

Injektion NVIDIA ist raus und der WebDriver deinstalliert und deaktiviert. SMBIOS ist imac14.2.

Der Rechner bootet im Verbose-Mode und wird plötzlich schwarz. Der Monitor gibt mir dann zu verstehen, dass er kein Signal erhält. Ich habe den Rechner mal mit DisplayPort und einmal mit HDMI gebootet.

Edit_15:50 Uhr: Inzwischen bleibt der Rechner hier stehen:

```
DYLIB_FIPS_POST: AES_CBC_POST passed!  
DYLIB_FIPS_POST: AES_GCM_POST passed!  
DYLIB_FIPS_POST: AES_XTS_POST passed!  
DYLIB_FIPS_POST: TDES_CBC_POST passed!  
DYLIB_FIPS_POST: SHA_POST passed!  
DYLIB_FIPS_POST: HMAC_POST passed!  
DYLIB_FIPS_POST: RSA_POST passed!  
DYLIB_FIPS_POST: RSA_KEYGEN_POST passed!  
DYLIB_FIPS_POST: ECDSA_POST passed!  
DYLIB_FIPS_POST: ECDH_POST passed!  
DYLIB_FIPS_POST: FFDH_POST passed!  
DYLIB_FIPS_POST: DRBG_CTR_POST passed!  
DYLIB_FIPS_POST: DRBG_HMAC_POST passed!  
DYLIB_FIPS_POST: FIPS_USER_Space_POST Success!  
Waiting for DSMOS...  
Previous shutdown cause: 5  
IOGraphics flags 0x43  
NVDAShutdownWeb: Web  
HID: Legacy shim 2  
DSMOS has arrived  
prevent idle sleep list: IODisplayWrangler+ (1)  
NVDAGK100HAL loaded and registered  
IOPPF: XCPM mode  
unexpected session: 100000 uid: -1 requested by: 36  
AppleKeyStore: operation failed (pid: 36 sel: 7 ret: e00002c2 '-536870206')  
Sound assertion in AppleHDA driver at line 1664
```

HDMI senseye LED