

Erledigt

RX 560 taucht nicht in HWM auf

Beitrag von „revunix“ vom 24. September 2017, 02:05

Code

1. Index Refs Address Size Wired Name (Version) UUID <Linked Against>
2. 26 0 0xffffffff7f810de000 0x42000 0x42000 com.logitech.manager.kernel.driver (6.70.1) BF95D805-77E8-37EC-B75E-88BBCC75B710 <25 22 21 19 5 4 3>
3. 42 2 0xffffffff7f88404000 0x47000 0x47000 as.vit9696.Lilu (1.1.7) 66CAFC1D-ED32-34D8-BCC4-AD843E9F6A6F <7 5 4 3 2 1>
4. 43 0 0xffffffff7f8844b000 0xd000 0xd000 as.vit9696.WhateverGreen (1.0.4) F74F4CF9-EE92-3E80-95CA-1A30250C8395 <42 12 7 5 4 3 2 1>
5. 44 4 0xffffffff7f88458000 0x11000 0x11000 org.netkas.driver.FakeSMC (1759) 987B8DEE-6600-3463-BFFA-DF500771FA5B <11 7 5 4 3 1>
6. 45 0 0xffffffff7f88469000 0x8000 0x8000 as.vit9696.AppleALC (1.1.4) 3B33A9D0-1AFD-364B-BC93-945EA73BC261 <42 7 5 4 3 2 1>
7. 46 0 0xffffffff7f88471000 0x5000 0x5000 org.hwsensors.driver.CPUSensors (1759) 1204F31F-1308-3F9A-B509-0425FC789815 <44 7 5 4 3>
8. 58 0 0xffffffff7f88477000 0x8000 0x8000 org.hwsensors.driver.ACPI Sensors (1759) FA4DF6C0-0D3A-3CE2-8569-0AB2C84053E7 <44 11 7 5 4 3>
9. 65 0 0xffffffff7f88481000 0x12000 0x12000 org.hwsensors.driver.GPUSensors (1759) ABDC14A9-7D25-3608-A129-A039C80468F6 <44 12 11 7 5 4 3>
10. 66 0 0xffffffff7f88496000 0xd000 0xd000 org.hwsensors.driver.LPC Sensors (1759) 46F77040-FA0F-3AEC-8330-E776B2D56C60 <44 12 11 7 5 4 3>
11. 74 0 0xffffffff7f884a3000 0xf000 0xf000 com.insanelymac.AtherosE2200Ethernet (1.1.1) 3AB7E0E7-BD2A-3EF3-815D-1A778D7E6547 <70 12 5 4 3 1>
12. 126 0 0xffffffff7f80d94000 0x7000 0x7000 org.pqrs.driver.Karabiner.VirtualHIDDevice.v040800 (4.8.0) E93C6B3D-9BBE-3579-97E1-4B6F51B8A527 <21 5 4 3 1>
13. 140 0 0xffffffff7f884b2000 0x3000 0x3000 com.radiosilenceapp.nke.filter (2.2) 3A2ED084-A6E7-3BEB-A0EC-1B7DE0EB41F6 <4 1>

Alles anzeigen

Bitte.