

Erledigt

Nach update von 10.12.4 auf 10.12.6 bleibt Bildschirm schwarz.

Beitrag von „Rambo45“ vom 13. Oktober 2017, 12:29

Hallo Jungs, war zu voreilig habe von 10.12.4 auf 10.12.6 combo update gemacht und jetzt bekomme ich schwarzen Bildschirm. Das ist letzte anzeige was ich sehen kann. Verwende clover 3677.

```
000002.254567 AppleUSBHostResources0: AppleUSBHostResources::allocateDownstreamBusCurrentGated: assuming successful wakeUnits 10
0 sleepUnits 0
000002.278693 AppleUSBHostResources0: AppleUSBHostResources::allocateDownstreamBusCurrentGated: assuming successful wakeUnits 10
0 sleepUnits 0
Darwin Bootstrapper Version 4.0.0; Sun May 7 19:34:52 PDT 2017; root:/libexec/AppleUSBHostResources-972.70.1-4/launchd/RELEASE_X86_64
boot-args = -v darkwake=0 kext-dev-mode=1 rootless=0
Warning: couldn't block sleep during cache update
Warning: proceeding w/o DiskArb
/dev/disk1s2 on / (hfs, local, journaled)
bash: /etc/rc.server: No such file or directory
dylib_integrity_POST_OSK: DYLIB path: /usr/lib/system/libcorecrypto.dylib
dylib_integrity_POST_OSK: MAC generated : (691689c391db2bc61a3839109de1b538c8f58b5aa14e69cdf6d7836ddc2f6a6d)
dylib_integrity_POST_OSK: On file x86_64: (691689c391db2bc61a3839109de1b538c8f58b5aa14e69cdf6d7836ddc2f6a6d)
DYLIB_FIPS_POST: dylib_integrity_POST passed!
DYLIB_FIPS_POST: AES_ECB_POST passed!
DYLIB_FIPS_POST: AES_CBC_POST passed!
DYLIB_FIPS_POST: AES_GCM_POST passed!
DYLIB_FIPS_POST: AES_XTS_POST passed!
DYLIB_FIPS_POST: TDES_CBC_POST passed!
DYLIB_FIPS_POST: HMAC_POST passed!
DYLIB_FIPS_POST: RSA_ENC_DEC_POST passed!
DYLIB_FIPS_POST: RSA_SIG_POST passed!
DYLIB_FIPS_POST: ECDSA_POST passed!
DYLIB_FIPS_POST: ECDH_POST passed!
DYLIB_FIPS_POST: FFDH_POST passed!
DYLIB_FIPS_POST: DRBG_CTR_POST passed!
DYLIB_FIPS_POST: DRBG_HMAC_POST passed!
DYLIB_FIPS_POST: FIPS_USER_Space_POST Success!
000002.776587 AppleUSBHostResources0: AppleUSBHostResources::allocateDownstreamBusCurrentGated: assuming successful wakeUnits 15
0 sleepUnits 0
000002.849635 AppleUSBHostResources0: AppleUSBHostResources::allocateDownstreamBusCurrentGated: assuming successful wakeUnits 15
0 sleepUnits 0
USBMSC Identifier (non-unique): 051K64NP6P0CG5J 0x8564 0x1000 0x1100, 2
Waiting for DSMOS...
IOGraphics flags 0x43
NVDRStartupWeb: Official (forced)
NVDRG100HPL: loaded and registered
prevent idle sleep list: IODisplayWrangler+ (1)
Sound assertion in AppleHDACodecGeneric at line 367
HID: Legacy shim 2
HID: Legacy shim 2
unexpected session: 100000 uid: -1 requested by: 38
AppleKeyStore: operation failed (pid: 38 set: 7 ret: e00002c2 '-536870206', -1, 100000)
USBMSC Identifier (non-unique): 20060413092100000 0xbda 0x151 0x5195, 2
hfs: Removed 0 orphaned / unlinked files and 1 directories
hfs: mounted Samsung SSD 840 on device disk0s2
busy timeout(0), (66s), kextd wait(0): 'AppleACPICPU'
█
```