

Erledigt

BCM94352HMB + Sierra 10.13 kein AirDrop mehr???

Beitrag von „al6042“ vom 19. November 2017, 13:11

Das kommt darauf an, welche Kexte du tatsächlich benutzt.

Die Kombi BrcmFirmwareRepo und BrcmPatchRAM2 sollten, auch laut Aussage von Rehabman, unter /L/E oder /S/L/E eingesetzt werden.

Die Kombi BrcmFirmwareData und BrcmPatchRAM2 läuft auch aus der EFI heraus...

Auf meinem Kabylake brauche ich keinen der Kombis, da es dort OOB funktioniert.

Apple Bluetooth Software Version: 6.0.0f1

Hardware, Features, and Settings:

Name:	al6042-iMac
Address:	a4-5e-60-d6-c1-34
Bluetooth Low Energy Supported:	Yes
Handoff Supported:	Yes
Instant Hot Spot Supported:	Yes
Manufacturer:	Broadcom
Transport:	USB
Chipset:	20703A1
Firmware Version:	v153 c4801
Bluetooth Power:	On
Discoverable:	Off
Connectable:	Yes
Auto Seek Pointing:	Off
Remote wake:	Off
Vendor ID:	0x05AC
Product ID:	0x8290

Auf meinem Skylake habe ich die erste Kombi unter /L/E abgelegt.

Apple Bluetooth Software Version: 6.0.0f1

Hardware, Features, and Settings:

Name:	al6042-iMac17
Address:	ac-d1-b8-bf-c9-8e
Bluetooth Low Energy Supported:	Yes
Handoff Supported:	No
Instant Hot Spot Supported:	No
Manufacturer:	Broadcom
Transport:	USB
Chipset:	20702A3
Firmware Version:	v14 c5668
Bluetooth Power:	On
Discoverable:	Off
Connectable:	Yes
Auto Seek Pointing:	Off
Remote wake:	On
Vendor ID:	0x0A5C
Product ID:	0x216F

Wichtig ist, dass in deinem Systembericht nicht die Firmware-Version v4096 angezeigt wird:

Zitat

If the version number is "4096", this means no firmware was updated for your device and it will not work properly.