


Erledigt


Sierra Installation auf X99 i7 5820k Rechner????

Beitrag von „abebem87“ vom 17. Januar 2018, 16:19

tscsync? was ist das?

Hier Screenshots ->





```
0x\ptioFix2Drv: Starting overrides for \System\Library\CoreServices\boot.efi
Using reloc block: no, hibernate wake: no
Error allocating 0x11ad9 pages at 0x000000001e7a2000 alloc type 2
Couldn't allocate runtime area
Boot failed, sleeping for 10 seconds before exiting...
```