

Erledigt

USB und Audio Problem auf GA-Z97NG5

Beitrag von „Xaser666“ vom 6. März 2018, 19:56

Index Refs Address Size Wired Name (Version) UUID <Linked Against>

36 1 0xffffffff7f82f8e000 0x19000 0x19000 as.vit9696.Lilu (1.2.2) B43828BB-6A20-3D60-AF53-C2FEE9FE0850 <7 5 4 3 2 1>

39 0 0xffffffff7f82fc8000 0xca000 0xca000 as.vit9696.AppleALC (1.2.2) C581E250-A491-3949-93D7-1EFBF529898F <36 7 5 4 3 2 1>

40 2 0xffffffff7f83092000 0x11000 0x11000 org.netkas.driver.FakeSMC (1759) 987B8DEE-6600-3463-BFFA-DF500771FA5B <11 7 5 4 3 1>

41 0 0xffffffff7f830a3000 0x5000 0x5000 org.hwsensors.driver.CPUSensors (1759) 1204F31F-1308-3F9A-B509-0425FC789815 <40 7 5 4 3>

57 0 0xffffffff7f82094000 0x5000 0x5000 org.rehabman.driver.FakePCIID (1.2.2) 1CAF4288-DB26-32CB-9F06-4165AADA8088 <12 7 5 4 3 1>

63 0 0xffffffff7f830a9000 0xd000 0xd000 org.hwsensors.driver.LPCSensors (1759) 46F77040-FA0F-3AEC-8330-E776B2D56C60 <40 12 11 7 5 4 3>

69 0 0xffffffff7f830b6000 0x8000 0x8000 com.insanelymac.AtherosE2200Ethernet (2.2.2) 14D6BA10-9384-33D1-B0D1-DA26C1DD2982 <16 12 5 4 3 1>

100 0 0xffffffff7f80e46000 0x4000 0x4000 com.intel.driver.EnergyDriver (2.0) 7FE9AF4A-A8C2-3099-A956-971DDC86A467 <7 5 4 3>