

Erledigt

DW1560: Bluetooth-Kummer...

Beitrag von „Harper Lewis“ vom 9. März 2018, 12:25

Kannst du mal bitte einen Screenshot machen, auf dem man das Gerät aufgeklappt im IORegExplorer sehen kann? Mich würde mal interessieren, welcher Treiber geladen wird (IOClass, CFBundleIdentifier...). Unter *Bluetooth USB Host Controller@Irgendwas* ist das meist der zweite Eintrag.

Fast vergessen: Der USB-Port, an dem der Bluetooth-Krams hängt (also z.B. HS06) sollte vom Typ USBConnector 0xff sein (ebenfalls ersichtlich im IORegExplorer).

Die KextsToPatch-Einträge sind auch veraltet, man sollte mittlerweile den kompletten BundleIdentifier benutzen, also z.B.

```
com.apple.driver.AirPort.Brcm4360 statt AirPortBrcm4360.
```

Noch ein Nachtrag:

Zitat

BrcmBluetoothInjector.kext

To be used for OS X 10.11 or newer. This kext is a simple injector... it does not contain a firmware uploader. Try this kext if you wish to see if your device will work without a firmware uploader. Do not use any of the other kexts (BrcmPatchRAM, BrcmPatchRAM2, BrcmFirmwareRepo, or BrcmFirmwareData) with this kext.

Also:BrcmBluetoothInjector.kext raus.