

Erledigt

Rechenknecht hat Bauchweh - KextUtility killt Rechner

Beitrag von „al6042“ vom 22. Juli 2018, 21:12

Es empfehlen sich grundsätzlich folgende EFI-Treiber:

| | |
|-----------------------------|-----------------------|
| ▼ drivers64UEFI | 29. Jun 2018 at 18:37 |
| ■ ApfsDriverLoader-64.efi | 29. Jun 2018 at 05:20 |
| ■ AppleImageCodec-64.efi | 29. Jun 2018 at 05:20 |
| ■ AppleKeyAggregator-64.efi | 29. Jun 2018 at 05:20 |
| ■ AppleUITheme-64.efi | 29. Jun 2018 at 05:20 |
| ■ AptioInputFix-64.efi | 29. Jun 2018 at 05:20 |
| ■ AptioMemoryFix-64.efi | 29. Jun 2018 at 05:20 |
| ■ DataHubDxe-64.efi | 29. Jun 2018 at 05:20 |
| ■ FirmwareVolume-64.efi | 29. Jun 2018 at 05:20 |
| ■ FSInject-64.efi | 29. Jun 2018 at 05:20 |
| ■ SMCHelper-64.efi | 29. Jun 2018 at 05:20 |
| ■ VBoxHfs-64.efi | 29. Jun 2018 at 05:20 |
| ▲ ACPI | 29. Jun 2018 at 18:35 |