

B85-HD3 Problem (Здравствуйте!)

Post by “sergeylogachev” of Sep 2nd 2018, 7:36 pm

I made DevProp.ffs in the BIOS, but DevProp.plist will not inject. Do not throw off an example of injection recipe DevProp.plist