

Erledigt

MSI G41M-P25 Problem

Beitrag von „P4Zi“ vom 25. Januar 2013, 00:01

Für die alte Signatur hättest du Google benutzen können.

So jetzt nochmal mit neuer Signatur, obwohl ich es oben auch schon alles genannt hatte.

Kann gerade kein Foto machen, versuche den Fehler so gut es geht zu beschreiben, bzw. noch besser.

Zitat

```
Darwin      Kernel      Version      12.2.0:      #Datum#Uhrzeit;root:xnu-2050.18.24-
1/RELEASE_X86_64
vm_page_bootstrap: 1005496 free pages and 34888 wired pages
kext submap [#Speicheradressen], kernel text [#Speicheradressen]
zone leak detection enabled
standard timeslicing quantum is 10000 us
standard background quantum is 2500 us
mig_table_mac_displ =74
corecrypto.kext started!
Running kernel space in FIPS MODE
Plist hmac value is #Hexadezimalcode
Computed hmac value is #Hexadezimalcode
corecrypto.kext FIPS integrity POST test passed!
corecrypte.kext FIPS AES CBC POST test passed!
corecrypto.kext FIPS TDES CBC POST test passed!
corecrypto.kext FIPS SHA POST test passed!
corecrypto.kext FIPS HMAC POST test passed!
corecrypto.kext FIPS ECDSA POST test passed!
corecrypto.kext FIPS DRBG POST test passed!
corecrypto.kext FIPS POST passed!
NullCPUPowerManagement::init: properties=#Speicheradresse
NullCPUPowerManagement::start
calling mpo_policy_init for Sandbox
Security policy loaded: Seatbelt sandbox policy (Sandbox)
calling moo_policy_init for Quarantine
```

Security policy loaded: Quarantine policy (Quarantine)
calling mpo_policy_init for TMSafetyNet
Security policy loaded: Safety net for Time Machine (TMSafetyNet)
Copyright (c) 1982bla
The Refents of the bla

MAC Framework successfully initialized
using 16384 buffer headers and 10240 cluster IO buffer headers

Alles anzeigen

So das ist alles was ich hier sehe 😊 Puuuhh...

MfG