

OpenCore Bootloader

Beitrag von „Yooyo“ vom 10. Juni 2019, 08:05

I'm very upset about OC because he never supports my XPS 15 9550. My configuration is as follows:

<https://www.amazon.com/DELL-XP...Z-3840X2160/dp/B01B9TQR7K>

Screen Size 15.6 inches

Screen Resolution 3840x2160

Processor 3.5 GHz Intel Core i7

RAM 16 GB

Memory Speed 2133.00

Hard Drive 512 GB flash_memory_solid_state

Graphics Coprocessor NVIDIA GeForce GTX 960M

Chipset Brand nvidia

Card Description dedicated

Graphics Card Ram Size 2 GB

Wireless Type 802.11ab, Bluetooth

Brand Name Dell

Series DELL XPS 15 - 9550

Item model number XPS 15 - 9550

Hardware Platform PC

Operating System Windows 10

Item Weight 3.9 pounds

Product Dimensions 9.3 x 14.1 x 0.7 inches

Item Dimensions L x W x H 9.27 x 14.06 x 0.66 inches

Processor Brand Intel

Processor Count 4


Computer Memory Type DDR4 SDRAM

Flash Memory Size 512 GB

Hard Drive Interface Serial ATA

Batteries 1 Lithium ion batteries required.

My CPU is Skylake platform, and I am always stuck in “ **Apple USB Legacy Root:: init: enabling legacy matching** “. I try to repair it through OC's Release UsbOwnership, but unexpectedly it doesn't work. It's still a USB .And it's normal for me to open FixOwnership under Clover, but OC disappointed me.



Code

1. <key>USB</key>
2. <dict>
3. <key>FixOwnership</key>
4. <true/>
5. <key>Inject</key>
6. <false/>
7. </dict>

At present, the SMBIOS I set up is 13.3, and I'm already very frustrated because he can't get into the system all the time. And one thing to note is that my Clover works very well. Another thing that bothers me is the order of kext. I really don't know how to adjust it, because I've been tossing and turning hundreds of times every day and night because of this problem.

Below is my successful Clover [CLOVER OK.zip](#) and my completely failed OC boot file [!OC.zip](#). I hope you can help me. Thank you very much.