

# **Alienware m15 R1 - Dual GPU Gaming Notebook - lauffähige Konfiguration (EFI inside)**

**Beitrag von „dududududu“ vom 3. Dezember 2019, 14:49**

Hi sir, I'm getting stuck on this line during first boot (usb) . Could you show me how to create usb boot to install mac catalina, please? Thank you.

...:pci8086,a369 SSCN not implemented in ACPI tables  
dooI2CControllerNub::pci8086,a369 FMCN not implemented in ACPI tables  
dooI2CControllerDriver::pci8086,a369 Warning: Error getting bus config, using  
rtual IOReturn IONVMeController::CreateSubmissionQueue(uint16\_t, uint8\_t)::  
rtual IOReturn IONVMeController::CreateSubmissionQueue(uint16\_t, uint8\_t)::2  
rtual IOReturn IONVMeController::CreateSubmissionQueue(uint16\_t, uint8\_t)::28  
fs\_module\_start:1683: Load: com.apple.filesystems.apfs, v1412.11.7, apfs-1412.  
dooI2CControllerDriver::pci8086,a368 Warning: Error getting bus config, using  
dooI2CControllerDriver::pci8086,a368 Publishing device nubs  
dooI2CControllerDriver::pci8086,a368 Found I2C device: MSFT0001  
dooI2CControllerDriver::VoodooI2CDeviceNub Could not find an I2C Serial Bus de  
ApplePS2Controller: Notification consumer published: ApplePS2Controller  
VoodooI2CControllerDriver::pci8086,a368 Could not initialise nub for MSFT0001  
VoodooPS2SynapticsTouchPad: Version 1.9.2 starting on OS X Darwin 19.0.  
ApplePS2Controller: Notification consumer published: ApplePS2Keyboard  
VoodooPS2Mouse: Version 1.9.2 starting on OS X Darwin 19.0.  
VoodooPS2Trackpad starting: Synaptics TouchPad reports type 0x47, version 9.16  
ApplePS2Controller: Notification consumer published: ApplePS2SynapticsTouchPad