

HP Laptop booten OC Fehler

Beitrag von „OSX-Einsteiger“ vom 21. Mai 2020, 16:58

@[Hecatomb666](#)

So gehe ich grundsätzlich vor

1. Nach der CPU [5-8265U](#) Googeln

Geräteerkennung	3EA0, 3EA1
-----------------	------------

2. Jetzt wird Interessant <https://github.com/acidanthera...nnectors-patches-with-weg>

Also habe ich mal diese nach der Device 3EA5 dementsprechend die Platform_ID raus gesucht.

Intel UHD Graphics 610-655 (Coffee Lake processors)

Supported since macOS 10.14

CFL framebuffer list:

- 0x3EA50009 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E920009 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E9B0009 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3EA50000 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E920000 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E000000 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E9B0000 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3EA50004 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3EA50005 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3EA60005 (mobile, 3 connectors, no fbmem, 58 MB)
- 0x3E9B0006 (mobile, 1 connectors, no fbmem, 39 MB)
- 0x3E9B0008 (mobile, 1 connectors, no fbmem, 58 MB)
- 0x3E9B0007 (desktop, 3 connectors, no fbmem, 58 MB)
- 0x3E920003 (desktop, 0 connectors, no fbmem, 1 MB)
- 0x3E910003 (desktop, 0 connectors, no fbmem, 1 MB)
- 0x3E9B0003 (desktop, 0 connectors, no fbmem, 1 MB)
- 0x9BC80003 (desktop, 0 connectors, no fbmem, 1 MB)
- 0x9BC50003 (desktop, 0 connectors, no fbmem, 1 MB)
- 0x9BC40003 (desktop, 0 connectors, no fbmem, 1 MB)