

ASUS Prime Deluxe II mit 10980XE

Beitrag von „TerminalStrip“ vom 22. August 2020, 15:01

Hello Friend,

I had already written to you in the past.

I have an X299 Prime deluxe 2 + i9 10920X motherboard

My system works, but I have two problems:

1. Thunderbolt / Usb C only works if I boot with a device inserted

2. I have a Firewire card which is detected in the IO REG but NOT in System Profiler and it doesn't work

Can you tell me how I can solve?

Thank you