

# csr-active-config Eintrag + Big Sur Installation Frage

Beitrag von „kexterhack“ vom 3. Januar 2021, 00:27

Klar danke

Hab hier beim Sample plist compare eine abweichung gefunden

Nur komisch, dass ich vor wenigen stunden erst geupdatet habe und gerade die alte gesicherte efi vor dem NVRAM Reset kopiert habe und dennoch diese abweichung bleibt.

Werde das mal ändern und sehen ob es wieder läuft ohne stick.

```
#####  
#                OC Config Compare                #  
#####  
  
Checking for values missing from User plist:  
  
config.plist -> NVRAM -> Add -> 7C436110-AB2A-4BBB-A880-FE41995C9F82 -> prev-lang:kbd - Type Difference: String --> Data  
config.plist -> UEFI -> Audio -> PlayChime - Type Difference: Boolean --> String  
  
Checking for values missing from Sample:  
  
Sample.plist -> DeviceProperties -> Add - Missing Key: PciRoot(0x0)/Pci(0x1,0x0)/Pci(0x0,0x0)  
Sample.plist -> NVRAM -> Add -> 7C436110-AB2A-4BBB-A880-FE41995C9F82 -> prev-lang:kbd - Type Difference: Data --> String  
Sample.plist -> UEFI -> Audio -> PlayChime - Type Difference: String --> Boolean  
  
Press [enter] to return...█
```