

Gigabyte Aorus B550 Elite V2 - Ryzen 9 5900X - RX 580 - MacOS 12.1 Monterey OC 0.7.6 EFI

Beitrag von „apfel-baum“ vom 8. Januar 2022, 18:02

hello [kimball](#) , and 

well done, issues about bluetooth - monterey has an seperatly thread [Sammelthread für BT Probleme unter Monterey](#)

sound problems belong in most cases to an alc id, if you know which chip is used for, you're able to try the ids of it -and with more or less duration it were the right one - and sound works. maybe it is an usb-port mapping problem issue too

greetz