

# **Ryzentosh - Auros B550i PRO AX - "3,6GHz Unbekannt" fix ?**

**Beitrag von „fabiosun“ vom 8. August 2022, 15:23**

could you try to disable feature unlock kext and SMCADProcessor kext and innie.kext? then reset Nvram again and see?

and also from terminal:

```
sysctl -n machdep.cpu.brand_string
```