

x299 pro/se freeze in Monterey or Ventura

Beitrag von „kaneske“ vom 28. November 2022, 19:41

You are going with XCPMConfigLock via OpenCore instead of using it unlocked via BIOS? Why do you do so?

Is there no Option for that?

Must be there, that might be the issue.

Quite much renames in ACPI Section, do you really need them? What's your EFI built from? Full ACPI Patch based on the origin one?

[startergo](#)

Looked for that in your Textfile: found it and it is enabled, has to be disabled. Do so and don't forget to disable the Quirk in OC. Should solve your issues.