

In Arbeit

macOS Installation auf ASUS B550 CREATOR mit Ryzen 7 3700X & RX 5700XT

Beitrag von „fabiosun“ vom 23. Oktober 2025, 12:05

ID	Name	Version	Enabled	Value	Comment
10	AppleMCEReporterDisabler.kext	V1.2 AppleMCEReporterDisabler.kext	<input checked="" type="checkbox"/>	true	
11	USBToolBox.kext	V1.2.0 USBToolBox.kext	<input type="checkbox"/>	false	C
12	UTBDefault.kext	V1.0 UTBDefault.kext	<input type="checkbox"/>	false	
13	UTBMap.kext	V1.1 UTBMap.kext	<input type="checkbox"/>	false	
14	IntelBTPatcher.kext	V2.4.0	<input type="checkbox"/>	false	C

USB kexts are enabled?

Have you in your motherboard bios an option like 4G or UEFI?

are they set On?

If so you could delete npci=0x2000 bootarg

Have you tried also with kext i did (modified whatevergreen for tahoe on)?

AMD kernel patches are proper now.

I think problem are on USB mapping and Bios setting

I think also that some user with your seme deutch language could help better than me now 😊