


macOS 26 Tahoe auf den Hackintosh

Beitrag von „fabiosun“ vom 5. November 2025, 13:17

your motherboard has ALC4082 as audio controller

this is an USB audio and it is seen in OSX without any kext:



in some condition could be mandatory to map well USB port to see it:

XH00	P0TH	0x01E00000	0x0F	USB2	1	Unknown
XH00	P0TH	0x03E00000	0x0F	USB2	2	Unknown
XH00	P0TH	0x02E00000	0x0F	USB2	3	Unknown
XH00	P0TB	0x01F00000	0x10	Internal	1	12 Mbps AURA LED Controller
XH00	P0TB	0x03F00000	0x10	Internal	2	480 Mbps USB Audio
XH00	P0TB	0x02F00000	0x10	Internal	3	Unknown
XH00	P0T1	0x01000000	0x01	Internal	1	Unknown