Erledigt asus gl553vd

Beitrag von "mt-fr" vom 4. Juli 2018, 12:56

HI

I have as us gl553vd = I7 7700HQ - HD 630 (installed) + GTX 1050 Desktop model (i love to off full !!!) + mac os 10.13.6

i fix many things (touchpad model elan 1200 . hd 630 . screen light . lan . usb .speaker)

i have so necessary problem ! my cpu love to eat many power on battery and AC (go to 120W) and buttery work only for 2H and so bad for buttery working . i checked full and i found MR GPU (GTX 1050) is on and use power for off them i used graphics_REG-disable patch for DSDT after patch system boot and i was login to mac os next , after 25S fas speed go to max level (6000) but cpu work amazing only use 2W power !!!!!!! and battery work for 5H .

i get to file report , befor and after patching .

how can i fix speed fan ??

Beitrag von "mt-fr" vom 11. Juli 2018, 08:47

any one can't help me ?? <u>@anonymous writer</u> can you help me ?

Beitrag von "anonymous_writer" vom 11. Juli 2018, 09:16

I am not an expert for disabling the nvidia. I'll take a look anyway.

Please upload with and without you patch your ioreg. IORegistryExplorer

Beitrag von "mt-fr" vom 11. Juli 2018, 09:21

<u>@anonymous writer</u> in zip file you can find . it's full report file . (in the debug _ zzzz folder - in zip) now i get img (with out patch)

Beitrag von "anonymous_writer" vom 11. Juli 2018, 09:26

I have just seen. I'll look at this later.

Beitrag von "mt-fr" vom 11. Juli 2018, 09:31

Zitat von anonymous writer

I have just seen. I'll look at this later.

Zitat von mt-fr

@anonymous writer in zip file you can find . it's full report file . (in the debug _ zzzz folder - in zip) now i get img (with out patch)

thank you so much

only fan speed is my problem when i using patch . the fan has controller in windows by Asus gaming center

Beitrag von "anonymous_writer" vom 11. Juli 2018, 17:13

Hello <u>@mt-fr</u>,

I will look on that later when I have time. Put please do not pin someting on my pinboard.

Beitrag von "anonymous_writer" vom 11. Juli 2018, 20:30

As I told you, I am not an expert for this, but you can try this SSDT-2.aml. Copy it to the folder /EFI/CLOVER/ACPI/patched.

Beitrag von "mt-fr" vom 11. Juli 2018, 20:34

Zitat von anonymous writer

As I told you, I am not an expert for this, but you can try this SSDT-2.aml. Copy it to the folder /EFI/CLOVER/ACPI/patched.

thank you . your sddt i tested with out patch code = gtx is on but with patch = fan go to max level i gest file ioreg and MR. how expert nvidia in this forum ?

Beitrag von "anonymous_writer" vom 11. Juli 2018, 21:19

Please search with google for "[Guide] Disabling discrete graphics in dual-GPU laptops". Maybe I just did something wrong.

Nvidia still exist in your ioreg. You have to switch off PEG0. Some BIOS can do this also.

		data-theBook-the-roug = 10tervice = P00001					
4100100 B 20 0		-			4.1.3		
discontraction of an orthogenetic	recurrence.						
Real Of Choice - Choi	lay diliget			Anne -	Maximum 10 Regional 2		
	Reports.	100	10.00				
Maria Networkscholm(1) Networkscholm(2) Networkscholm(2) Networkscholm(2) Networkscholm(2)	 Britishardikas Britishardika Britishardika Britishardika Britishardika Britishardika Britishardika 	Anno Anno Anno Annoration Annoration	1. 000 101 00 00 00 101 00 00 101 00 100 1				
	14/10 M	ins.					
Project In (* 1817-1918)	an agen artest + Grean-getterrortes sete	No.	EXCENTION Internet internet in the second seco				
	1000 - 0 100 - 0 40 40 40-	-01 61 61 60-					
	and show other	1000	The second secon				
		Sec.	10 10 10 10 IN				
	A1170-14	Sec.	ALC				
		Dete:	- pc.0001/1007. fp/cmm.000406, 70007 v				
		Dete					
	GROUPING HOMESTIC	interior .	Init/antil				
	ercourgest	Burley.	ha				
	a share	100	ENCYMENT REPORTED FOR				
	OCE-procedute OCE-procedute	-	-01 80 80 80- Ref-101 Ref-101				
	printing	Serve .	#10.9 lb				
	Chang .		N. L. M.				
			ALL MARKED				
		Des .					

Beitrag von "anonymous_writer" vom 12. Juli 2018, 21:11

If you still have no luck then test this SSDT-2.aml again.



Beitrag von "mt-fr" vom 13. Juli 2018, 10:46

Zitat von anonymous writer

If you still have no luck then test this SSDT-2.aml again.



Hi

thank you but gtx is on .

i installed web nvidia app and used new config on clover after do i get new debug file in this file we can find better gtx , please check (gtx web deriver zip)

for example we can find in this file :



Beitrag von "anonymous_writer" vom 13. Juli 2018, 14:51

Maybe I understand something wrong, but that's great if the NVIDIA runs with the Webdriver.

Beitrag von "mt-fr" vom 13. Juli 2018, 14:57

Zitat von anonymous writer

Maybe I understand something wrong, but that's great if the NVIDIA runs with the Webdriver.

why gtx go to off ?

work with web nvidia but in system i can't see this work ! in system sys : chip model dram : !!! i have to work in this time :

off gtx

or

on gtx and use it

when off this fan speed go to max

when use web nvida on system can't see work . but pci app sys work for 3d !! how can i fix this ?

Beitrag von "anonymous_writer" vom 13. Juli 2018, 16:13

Please test to delete these files: AppleALC.kext ApplePolicyControl.kext IntelGraphicsFixup.kext Lilu.kext

ans use for this newer attached files.

Beitrag von "mt-fr" vom 13. Juli 2018, 17:01

Zitat von anonymous writer

Please test to delete these files: AppleALC.kext ApplePolicyControl.kext IntelGraphicsFixup.kext Lilu.kext

ans use for this newer attached files.

i change and i delete but i can't see any change in system

Beitrag von "anonymous_writer" vom 13. Juli 2018, 17:02

A pity, then unfortunately no further ideas from my side.

Beitrag von "mt-fr" vom 13. Juli 2018, 17:07

Zitat von anonymous writer

A pity, then unfortunately no further ideas from my side. 🥊

thank you man you many help and use many time for me

please check pv i sent pm.

Beitrag von "anonymous_writer" vom 15. Juli 2018, 19:51

Hi <u>@mt-fr</u>,

Attached SSDT-9.aml with _OFF.

And a second variant.

Beitrag von "mt-fr" vom 15. Juli 2018, 20:29



Hi thank you so much gtx is off with two file but fan speed on max level ! debug_31922.zip with 1 patch debug_31248.zip with 2 patch (on zip patch)

Beitrag von "anonymous_writer" vom 15. Juli 2018, 20:40

Currently I have no idea how to switch off the fan. Do you see this FAN in the HWMonitor? Maybe the fan have a PCI number that you can also switch _OFF.

https://bitbucket.org/RehabMan...fakesmc-kozlek/downloads/

Beitrag von "mt-fr" vom 15. Juli 2018, 20:55

Zitat von anonymous writer

Currently I have no idea how to switch off the fan. Do you see this FAN in the HWMonitor? Maybe the fan have a PCI number that you can also switch _OFF.

https://bitbucket.org/RehabMan...fakesmc-kozlek/downloads/

i haven't fan in HWM app . and i install many fan speed but in they app fan speed = -1rpm . but gtx is really off i can't see it

Beitrag von "anonymous_writer" vom 15. Juli 2018, 21:05

In this case my only idea is to unplug the fan from the motherboard.

You are using Kext FakeSMC GPUSensors.kext?

Beitrag von "mt-fr" vom 15. Juli 2018, 21:08

Zitat von anonymous writer

In this case my only idea is to unplug the fan from the motherboard.

.3

i have fan speed in bios and in windows only control and show with asus gaming center . can we find fan code in windows and use in mac or in linux ?

Beitrag von "anonymous_writer" vom 15. Juli 2018, 21:12

For sure you can. I just have no idea. I write if I find something.

You have to find the place where the fan is addressed in the DSDT or SSDT.

Beitrag von "anonymous_writer" vom 18. Juli 2018, 19:24

Hi <u>@mt-fr</u>,

Attached SSDT-9.aml with change _OFF to _PS3.



Beitrag von "mt-fr" vom 25. Juli 2018, 16:04

Zitat von anonymous writer

Hi <u>@mt-fr</u>,

Attached SSDT-9.aml with change _OFF to _PS3. Good luck 😎

thank you but doesn't worked and only we use off but when we use off , off all item in item we can see fan please search fan , you can see fan we most off all but with out fan

Beitrag von "anonymous_writer" vom 26. Juli 2018, 08:23

Yes, I can see fan in the SSDT-9.aml. Unfortunately, I have no idea how to switch off the fan. Sorry.

Beitrag von "anonymous_writer" vom 26. Juli 2018, 10:27

You may be able to solve the problem with this kext.

-wegnoegpu to disable external GPU (or add disable-external-gpu property to IGPU)

WhatEverGreen - Fix für alle Grafikkarten (AMD/Intel & Nvidia)

https://github.com/acidanthera/WhateverGreen

Beitrag von "mt-fr" vom 26. Juli 2018, 21:14

Zitat von anonymous writer

You may be able to solve the problem with this kext.

-wegnoegpu to disable external GPU (or add disable-external-gpu property to IGPU)

WhatEverGreen - Fix für alle Grafikkarten (AMD/Intel & Nvidia)

https://github.com/acidanthera/WhateverGreen

Alles anzeigen

thank you, man. where is for installing it? clover ?l

l/s/e ? l/e ?

Beitrag von "griven" vom 26. Juli 2018, 21:22

It's save to put it into Clovers Kext Dir and let Clover do the Work for you. Don't forget to place Lilu.kext there either...

Beitrag von "mt-fr" vom 27. Juli 2018, 14:41

ooooooh . not worked. Nvidia company sooooo bad company i don't love it

Beitrag von "anonymous_writer" vom 27. Juli 2018, 14:57

Same problem as before? Nvidia off and fan on high power?

Have you test the kext without the pached ssdt's?

Beitrag von "mt-fr" vom 27. Juli 2018, 17:08

Zitat von anonymous writer

Same problem as before? Nvidia off and fan on high power?

Have you test the kext without the pached ssdt's?

ΗI

I most sys in once thanks because of your help me all time.

I installed lilu kext by you "Für diesen Kext wird min Lilu.kext V1.2.6 benötigt." and copy it to the clover kexts

copy WhatEverGreen to the clover kexts

use -wegnoegpu disable-external-gpu in the config.

Beitrag von "anonymous_writer" vom 29. Juli 2018, 17:57

Please test with WhateverGreen.kext and Lilu.kext this PropertyInjector.kext. Copy this new Kext to "/EFI/CLOVER/kexts/Other" and add to clover the boot parameter in the picture.



This should increase VRAM and shut down the GPU. For your FAN issue , I am not sure if this help.

WhatEverGreen - Fix für alle Grafikkarten (AMD/Intel & Nvidia)

Lilu - Generic kext patcher (neue Grundlage für AppleALC 1.1.x und Shiki 2.x.x)

Beitrag von "mt-fr" vom 30. Juli 2018, 07:28

Edit by derHackfan: Vollzitat entfernt

HI now i can't boot system .my clover :

Beitrag von "anonymous_writer" vom 30. Juli 2018, 07:43

Test it without "Inject Intel" and without "ig-platform-id" in the clover config.plist.

Beitrag von "mt-fr" vom 30. Juli 2018, 08:05

Zitat von anonymous writer

Test it without "Inject Intel" and without "ig-platform-id" in the clover config.plist.

do it but system doesn't boot for boot i most boot with out whatevergreen and prop..... kexts

Beitrag von "anonymous_writer" vom 30. Juli 2018, 08:49

Please test this PropertyInjector.kext.

Beitrag von "mt-fr" vom 30. Juli 2018, 09:23

where are you ???/ i can't believe this . only use PropertyInjector.kext.zip with out whatevergreen because i can't boot it with whatevergreen and i get video and i do compress

for send

but when i boot with out that i see gtx 1050 !!!! so amazing with out install web driver and nvidiafixup !!! but it dosen't Vram

Beitrag von "anonymous_writer" vom 30. Juli 2018, 10:06

I do not really understand what you mean.

PropertyInjector.kext + WhateverGreen.kext + Webdriver > NVidia Works but without NVRAM?

With WhateverGreen.kext you do not need IntelGraphicsFixup.kext and NvidiaGraphicsFixup.kext. Both are already included in the WhateverGreen.kext. Therefore it is necessay to delete both.

Beitrag von "mt-fr" vom 30. Juli 2018, 10:10

PropertyInjector.kext > NVidia Works but without NVRAM? is right . whatevergreen doesn't work when use it system doesn't boot i can't install web diver when install it i can't boot system

Beitrag von "anonymous_writer" vom 30. Juli 2018, 10:17

Please make picture what you can see here.

		MacBook Pro			
T Handware	Video Card		- Teter		104
ATA.	Bullence State State or other			-	-
Auto	Carlored Stra Could Heat		040	PCM	Burton
Bustouth	The TRE Graphics 600		940	Burn III	
Camera					
Card Reader					_
Tancostics.					
< Asc Burning					>
Therest Cards					
Fibre Chennel					_
FinalWine	Geferce 07X 1050 met	de l			
Oraphics/Displays					
Hardware BAID	Chippert Model	Geforce OFX 1090 mobile			
Memory	5ee ()	GPU Control of the second se			
NVMExpress	Evel.	PCB Bullion			
PO	PCIe Lane Width:	+10			
Parallel SCSI	VEAM (Dynamic, Max):				
Popper	Vendori	WVIDIA (DV100e)			
Printers	Device (D)	Controlling Inc.			
545	Metal	Europertent, feature part mar/OE OPUFamily1 v3			
SATA/SATA Depress		The second			
525					
Storage					
Thursdarbolt					
1.58					
(Bridger					
W Mediantech					
Firment					
Locations					
Wolumes					
WWWW					
100-01					
T Software					
Accessibility					
Applications					
Components					
Screen Shot 1397-05-08 at Bild 4 von 5	11.50.46.prg				^ x

Beitrag von "mt-fr" vom 30. Juli 2018, 10:50

i can see this

Beitrag von "anonymous_writer" vom 30. Juli 2018, 11:03

And what happen with this kext under Intel HD? $\stackrel{ ext{constraint}}{ ext{constraint}}$

Beitrag von "mt-fr" vom 30. Juli 2018, 11:37

wooow you and your work are so amazing !! whatevergreen work for work it i removed intelgrapichfixup and nvidiagarepichfixup i used you new kext and now i have 2GB vram for 630 !! and i fix pci for show hd630.

Beitrag von "anonymous_writer" vom 30. Juli 2018, 12:43

Then please also test this PropertyInjector.kext.

Beitrag von "mt-fr" vom 30. Juli 2018, 12:50

so bad worked . all setting go to default hd630 now has 1.5 gb v ram and gtx1050 rename to can you use gtx 1050 Vram for hd630 my gtx1050 has 4 gb ram

Beitrag von "anonymous_writer" vom 30. Juli 2018, 12:56

Then this version.

Beitrag von "mt-fr" vom 30. Juli 2018, 13:06

i can't see any changing . i have 2 gb Vram anf gtx on last mode (has not any ram) can you use gtx1050 Vram for hd630 ?

Zitat von mt-fr

Hi thank you but gtx is on .i installed web nvidia app and used new config on clover after do i get new debug file in this file we can find better gtx , please check (gtx web deriver zip)for example we can find in this file :

	1011 B 8			1.2			
	Apres		The second se	100 1			
	Address of the second		1.810				
	1 Carlos da	The state of the s	Tan Tan				
		100 Bolton 100 Bolton	in and in the second second				
		and the second					
	and the second						
	Units and Units	1000	AN AREA IN A REAL AND				
	A DECEMBER OF	ALC: NO	ter of the second secon				
	100000	-	and a second sec				
	Capacitation and Capaci	The second second					
	TRUE AND A CONTRACTOR OF A	of the other states	Edge El				
	Construction and	Of Sec. 14	the ta				
			ing - Array Tanker's				
	1 March 1997	100	11 11 11 11 11 11 11 11 11 11 11 11 11				
	1 selected and the selected as	TOTAL CONTRACTOR OF TAXABLE	10 10 10 10 10 10 10 10 10 10 10 10 10 1				
	1 mm	the second second					
	1992/100/00	at the second	NAT IN				
	1 August Marcalaus	14	P 7				
	- and the second second			111			
	1 1 200h	and the second	in the local sector of the				
	1 Martin Barrier B						
	C team	10.000	- 100				
	Logar La Contra						
	100						
	17 Dagas Bas						
	March 18			2 1.000			
-			12				
_			These basics a				
disc als	time d'date divis displate displ		The second secon				
	ally statistical			codo (pr	awar ucina	and) c	an wou use it
		tion to the second s	a contract of the second se	coue (pu	Jwer using	janu) C	all you use it
							-
_	1.00						
	1 Marca and 1 Marc	-					
	1 Your Contract of		1.2.8				
	- termination of the second seco	-	Contrast 1 of a strategy				
	(Carrierona)	a shake his					
	- unit electric - term	Sectors has b	P*				
	Total Control of Contr	the state of the s					
	- and the second second		-				
	100		12				
	- West working a						
	1 A STATE OF THE S	100 m					
	- AND COMPANY OF A	and the second					
	100 East 10						
	Contractor and						
	100						
	The second secon						
	727		111				
	1 Contract C						
	- Chear						
	(Tapa to						
	1999941) 1998			and limit	aty nowor	ucing 2	
-	1.00		40/07/# 1444	anu minit	ycz power	using :	
					- .	-	

Beitrag von "anonymous_writer" vom 30. Juli 2018, 13:31

I have to take a closer look at the NVIDIA and have to test a few things on my computer. After that I will able to give you an answer.

Before, please also test this PropertyInjector.kext.

Beitrag von "mt-fr" vom 30. Juli 2018, 13:47

i tested it i feel small changed in power using important problem is power using . can you limit more ? limit to 1 w using ? now use 4 w or 3.8 w using by gtx but other item is soooooo good . hdmi now work with out nvidia web = gtx 1050 is so right install with you

Beitrag von "anonymous_writer" vom 30. Juli 2018, 14:00

Can you please show me again a picture from here?

Card		 Туре	Driver installed	Slot
GeForce GTX 1050 mobil	le .	Graphik Controller	Yes	Delte-
Intel HD Graphice830		Graphik Controller	Yes	Buitt
Galarra GTX 1950 mai	-			
Name: Type: Driver Installed: MSI:	display Graphik Controller Wes			
But: Set: Vendor ID: Device ID: Subsystem Vendor ID: Subsystem ID: Revice ID:	PCI Builton Dartobe Dartobe Dartobe Dartobe Dartobe			
Link Wigth: Link Speed:	116 8.0 GT/s			

Beitrag von "mt-fr" vom 30. Juli 2018, 14:04

yes . i most take photo and send it's so small work when watch your work .

Beitrag von "anonymous_writer" vom 30. Juli 2018, 14:31

I have to test few things. I will write after this test again.

Beitrag von "mt-fr" vom 30. Juli 2018, 14:58

thank you . goood job .do you like to send full debug file ?

Beitrag von "anonymous_writer" vom 30. Juli 2018, 15:10

At the moment I do not need them.

Beitrag von "anonymous_writer" vom 31. Juli 2018, 21:13

Again one Test. What can you see under PCI with this Kext?

Beitrag von "mt-fr" vom 1. August 2018, 07:36

Hi i get file by system report . now i have 1.5 gb Vram for hd630 and only hd630 work on graphic tab and i can see 1050 on pci but sys not install driver

Beitrag von "anonymous_writer" vom 1. August 2018, 07:56

Please Test again and send me picture from PCI.

Beitrag von "mt-fr" vom 1. August 2018, 11:31

Beitrag von "adra" vom 1. August 2018, 23:57

I have a similar laptop the GL753VD with the same hardware just a 17" screen size. I tried to boot High Sierra with your EFI folder and followed your steps and I have trouble booting MacOS after installing it. It seems to be too many kexts being loaded. What is your current config.plist that you are using at the moment. Im booting in UEFI mode with GPT partitions. How can I help you guys troubleshoot this and hopefully get it running on my ASUS too.

Beitrag von "anonymous_writer" vom 2. August 2018, 07:52

Hello @adra,

The problem from mt-fr is that the Gforce GTX 1050 mobile is not compatible to OSX. He can switch off the Nividia, but then the fan of the Nividia go to max speed. No possibility to switch off both, Nvidia and Fan.

Hello <u>@mt-fr</u>,

Here again a PropertyInjector.kext which contains the eGPU OFF variable for the Whatevergreen Kext. Test it with the boot parameter "-wegnoegpu" in clover. If this does not work then please write here:

https://www.insanelymac.com/fo...ffer-patching-for-mojave/

Maybee they can help you to switch OFF your eGPU with the Whatevergreen Kext.

Beitrag von "mt-fr" vom 2. August 2018, 11:47

Hi

thank you man . now i can see many changes pci work so full !! and show all item . but gtx use 4 w power on cpu package power .

i think we can't off gtx , we should limit gtx power and set it power k]on low using

Beitrag von "anonymous_writer" vom 2. August 2018, 14:46

The only way to reduce the wattage is turning off nvidia and the fan from the nvidia. Maybe it will be help if you also use the SSDT-9.aml.

It seems to be that WhateverGreen.kext do not work. Therefore please ask on the insanelymac side if someone from the developer of the kext can help you.

Thanks for the PCI list goes to @NoirOSX . He include this devices in the PropertyInjector.kext.

Beitrag von "mt-fr" vom 2. August 2018, 15:05

ΗΙ.

you tell right . i use ssdt-9 with _PS3 but not to do any change to power using by gtx . but but your work so nice and temp now 2 C or 5 C lower then past and power using 600MW lower than past and HDMI WORKING with out nvidiaweb it's so nice . i love your work . i'm not on level for says thank you , you use your time for me , thank you . @NoirOSX thank you .



Beitrag von "NoirOSX" vom 2. August 2018, 16:05

Freut mich dass es geht 🙂

Beitrag von "mt-fr" vom 2. August 2018, 16:35

when i using PropertyInjector.kext my mac os so slow boot i get debug file . can you fix it ?

Beitrag von "anonymous_writer" vom 3. August 2018, 16:48

Try it after you delete these files.



From this files It is important that only one was installed. Otherwise, you get problems. OsxAptioFix2Drv-64.efi <> OsxAptioFix3Drv-64.efi <> OsxAptioFixDrv-64.efi <> OsxLowMemFixDrv-64.efi <> AptioMemoryFix.efi

Beitrag von "mt-fr" vom 3. August 2018, 17:19

i delete select file with red line ?

Beitrag von "anonymous_writer" vom 3. August 2018, 17:55

If this is a question, yes please.

Beitrag von "mt-fr" vom 4. August 2018, 09:16

Hi

i deleted iteme but system loud so low and i can't feel any change to speed for loud

Beitrag von "Schucha" vom 5. August 2018, 11:59

ich hab den gleichen laptop ...

habe einen stick erstellt mit 10.13.2 und unibeast aber ich komme einfach nicht durch die installation... der balken läuft voll durch aber wenn ich dann wieder übers uefi in clover boote zeigt er mir die erstellt partition nicht an ...

wieso?

wer kann weiterhelfen ?

danke

Beitrag von "al6042" vom 5. August 2018, 12:07

Auch hier der oft erwähnte Hinweis, dass die Beaster im Forum nicht unterstützt werden.

Das liegt z.B. auch daran, dass sie den aktuellsten Clover-Versionen gerne hinterherhinken und gerade in deinem Fall auch nicht den aktuellsten EFI-Treiber namens ApfsDriverLoader-64.efi mitführen.

Das "aktuelle" Unibeast 8.3.2 nutzt noch den Clover in der Version 4428, während der 4630 als aktuellste, offizielle Version vorliegt.

Dieser würde dein Problem sehr wahrscheinlich lösen.

Beitrag von "Schucha" vom 5. August 2018, 12:33

Okay top !! Dann ohne diesen scheiss...

edit:

- 1. mit diskmakerx Bootstick 10.13.5 erstellt
- 2. Neusten clover mit apfs driver installiert
- 3. Die kexte von mt-fr in other kopiert
- 4. Die ssdts in patched kopiert

5. nun stecke ich bei folgendem Abschnitt fest das dauert ewig

edit 2:

hat sich wohl einfach aufgehängt, habe über clover einfach nochmal reingebootet dann ist es durchgelaufen ...

Beitrag von "adra" vom 8. August 2018, 19:13

I'm trying to install High Sierra and cant get to the Install screen. Im using the latest clover released today (r4637), and High Sierra (10.13). I also updated my BIOS to the latest version from 304 to 307. It gets stuck half way on the apple logo screen. What <u>BIOS settings</u> you guys are using?

My current BIOS config is the following:

- Intel Virtualization Technology: Disabled
- Intel AES-NI: Disabled
- VT-d: Disabled
- Fast boot: Disabled
- CSM Support: Disabled
- Secure Boot: Disabled
- Legacy USB support: Disabled
- USB Mass Storage Driver Support: Enabled

Should Intel Virtualization Technology or CSM Support be enabled?

Sorry for not writing in German and thanks for any help you can provide.

Beitrag von "mt-fr" vom 9. August 2018, 17:57

use the install clover <u>https://github.com/Mohammadtag...erra-For-Asus-ROG-GL553VD</u> -----for install, most gtx go to off

Beitrag von "adra" vom 13. August 2018, 15:46

I have been testing and have made a bit lot of progress... I can now finally boot into High Sierra! Thanks to everyone! Specially to <u>@mt-fr</u>.

I am able to load clover in UEFI mode from my hdd and Install MacOS High Sierra from a usb stick after copying the CLOVER - INSTALL folder from your github repo to the efi partition in my hdd. I used the same config.plist file from your setup and had to delete several conflicting drivers from the drivers64UEFI folder and block some kext files to make it work.

\EFI\CLOVER\drivers64UEFI\EmuVariableUefi-64.efi \EFI\CLOVER\drivers64UEFI\CsmVideoDxe-64.efi \EFI\CLOVER\drivers64UEFI\OsxAptioFixDrv-64.efi \EFI\CLOVER\drivers64UEFI\OsxAptioFix2Drv-64.efi \EFI\CLOVER\drivers64UEFI\OsxAptioFix3Drv-64.efi \EFI\CLOVER\drivers64UEFI\OsxLowMemFixDrv-64.efi \EFI\CLOVER\drivers64UEFI\NvmExpressDxe-64.efi \EFI\CLOVER\drivers64UEFI\AppleImageCodec-64.efi \EFI\CLOVER\drivers64UEFI\AppleKeyAggregator-64.efi \EFI\CLOVER\drivers64UEFI\AppleUITheme-64.efi \EFI\CLOVER\drivers64UEFI\AptioInputFix.efi \EFI\CLOVER\drivers64UEFI\AptioMemoryFix.efi \EFI\CLOVER\drivers64UEFI\DataHubDxe-64.efi \EFI\CLOVER\drivers64UEFI\Fat-64.efi \EFI\CLOVER\drivers64UEFI\FirmwareVolume-64.efi \EFI\CLOVER\drivers64UEFI\FSInject-64.efi \EFI\CLOVER\drivers64UEFI\HFSPlus.efi \EFI\CLOVER\drivers64UEFI\HFSPlus-64.efi \EFI\CLOVER\drivers64UEFI\NTFS-64.efi \EFI\CLOVER\drivers64UEFI\OsxFatBinaryDrv-64.efi \EFI\CLOVER\drivers64UEFI\PartitionDxe-64.efi \EFI\CLOVER\drivers64UEFI\SMCHelper-64.efi \EFI\CLOVER\drivers64UEFI\UsbKbDxe-64.efi \EFI\CLOVER\drivers64UEFI\UsbMouseDxe-64.efi \EFI\CLOVER\drivers64UEFI\VBoxHfs-64.efi

After installing MacOS the machine automatically reboots and I can see that there are 2 new boot options one is the Mac Recovery partition and MacOS partition alongside Win10. I can now boot into Windows 10 and MacOSX!

How can I check if this laptop has Native NVRAM or not?

Beitrag von "adra" vom 22. August 2018, 14:08

After using <u>@mt-fr</u> EFI folder I still cant get the touchpad or Intel wfif to work 🐸

I've been using a usb mouse ever since I installed Mac and a Edimax 2.4Ghz wifi usb dongle to connect to internet.

The sound I can get working by replacing the AppleALC.kext with VoodooHDA.kext in Clover folder. The sound quality is good but the maximum voulume is low compared to Windows. I've read that it is normal when using Voodoo kext instead of the Realtek ALC audio drivers.

Voodool2C and Voodool2CHID kexts don't seem to work and if I dont block I2C OSX cant boot.

I think my DSDTs might need the Windows patch for Voodoo. Is the ELAN touchpad unsupported or is there anyone who got it working that can help?

Beitrag von "mt-fr" vom 23. August 2018, 11:18

only use my dsdt in GitHub and you most be remove kext (AppleIntelLpssL2C.kext and AppleIntelLpssI2CController.kext) in s/l/e and clean cache. wifi doesn't work and for sound use voodoo (UEFI mode) for elan search kext.

Beitrag von "mt-fr" vom 28. September 2018, 20:02

@anonymous writer hi
how are you ?
i worked on debug of PropertyInjector.kext ===>
can you enable gtx1050 ?
can you connect laptop fan to mac os for monitor fan speed ? (most i find fan id in windows ?)

Beitrag von "anonymous_writer" vom 28. September 2018, 20:22

Hi <u>@mt-fr</u>, please write more details. Which gtx1050? In your Laptop? Same Laptop as in the Title?

Beitrag von "mt-fr" vom 28. September 2018, 20:25

Edit by al6042 -> Please do not quote post, which came directly before you replied...

hi for my laptop gl553vd please .

in the past time you made kext for this laptop wit pci list but gtx1050 blocked i think for that mac os boot get long time to boot .

for fan i need monitor fan speed and control it in mac os , in windows i have ROG gaming center by Asus , this app can control fan in windows

Beitrag von "anonymous_writer" vom 28. September 2018, 20:41

give you an answer tomorrow. I'm just not on my Hacki.

Beitrag von "mt-fr" vom 28. September 2018, 20:48

Edit by al6042 -> Please do not quote post, which came directly before you replied...

now can't you Edit your kext ? and do renove gtx1050 block and add fan id to system ?

Beitrag von "anonymous_writer" vom 28. September 2018, 22:50

Hi <u>@mt-fr</u>,

please upload your current EFI. As a base for further changes.

Beitrag von "mt-fr" vom 28. September 2018, 22:58

my clover folder

when i removed the old dsdt file in patch folder elan 1200 hasn't worked

i send old dsdt file need to change dsdt file with new because old file for fx553 !! for that i get origin file now

====>

now fix it with ==>

Code

 # Patch to fix ELAN1200 _DSM method to make it work with Voodool2Cinto method label _DSM parent_label TPD0 remove_entry;into device label TPD0 insertbegin\nMethod (_DSM, 4, Serialized) // _DSM: Device-Specific Method ELAN1200 \n{\nlf (LEqual (Arg0, HIDG))\n{\nReturn (HIDD (Arg0, Arg1, Arg2, Arg3, HID2))\n}\n\nlf (LEqual (Arg0, TP7G))\n{\nReturn (TP7D (Arg0, Arg1, Arg2, Arg3, SBFB, SBFG))\n}\n\nReturn (Buffer (One)\n{\n0x00 \n})\n}\nend;

but i think it can work better than this . in windows work very well

Beitrag von "anonymous_writer" vom 29. September 2018, 14:45

I removed "disable-external-gpu" in the PropertyInjector.kext.

	w	or contraction of the second s		
▼GTX-1050		Dictionary	\$	6 Schlüssel/Wert-Paare
CFBundleidentifier		String	0	de.Brumbaer.PropertyInjector
IOClass		String	÷	PropertyInjector
IOMatchCategory		String	0	mhteejhgigiö
IOPCIPrimaryMatch		String	0	0x1c8d10de
IOProviderClass		String	0	IOPCIDevice
v Properties		Dictionary	0	5 Schlüssel/Wert-Paare
AAPL,slot-name		Daten	0	8 Bytes: 4275696C 74496E00
device_type		Daten	0	19 Bytes: 47726170 68696B20 436F6
disabie-external-gpu		Daten	0	418ylms 01000000
hda-gtx		Daten	0	10 Bytes: 6F6E626F 6172642D 3100
model		Daten	0	24 Bytes: 4765466F 72636520 475458
v HD-630		Dictionary	0	6 Schlüssel/Wert-Paare
CFBundleidentifier		String	0	de.Brumbaer.Propertylnjector
IOClass		String	0	Propertylnjector
IOMatchCategory		String	0	mhteejhgigiö
IOPCIPrimaryMatch		String	0	0x591b8086
IOProviderClass		String	0	IOPCIDevice

For the GTX-1050 you need the Nvidia Webdriver. Webdriver exist until today only up to High Sierra,

Beitrag von "mt-fr" vom 29. September 2018, 18:53

Edit by al6042 -> Do yourself a favor and do not quote post, which came directly before you replied...

thank you so much , can you off the hd630 ? can you add the fan to system with this kexts because add pci list

Beitrag von "anonymous_writer" vom 29. September 2018, 19:26

Why do you want to turn off the HD-630? You can usually do that via BIOS Setting.

To display the FAN in the PCI list, I need Device ID and Vendor ID from the FAN. Did you find them somewhere?

					Status RELEAS Miss
Vendor	Desire	Sub Ver	Bull Dev	Vendor Name	Device Name
0 0000	5904	1043	1520	Intel Corporation	Xeon E3-1200 v6/7th Gen Core Processor Heat Bridge/DRAM Registers
0 0000	5915	1043	1520	Intel Corporation	HD Graphics 620
0 1011	1903	1043	1520	Intel Corporation.	Xeon E3-1200 v5/E3-1500 v5/Eth Gen Core Processor Thermal Subsystem
O 8086	1060	1043	1520	Intel Corporation	Survise Point-LP Serial IO DC Controller #0
@ sces	102F	8086	7270	Intel Colporation	Survice Point-LP USB 3.0 (HC) Controller
@ 0000	9031	1043	1520	letel Corporation	Survise Point-LP Thermal subsystem
@ sces	9061	1043	1520	Intel Corporation	Survise Point-CP Serial XD QC Controller #1
0 1015	9003	1043	1520	Intel Corporation	Survise Point-CP SASA Controller (AHC) mode)
0 1015	9034	1043	1520	lettel Corporation	Survise Point-LP CSME HECH #1
0 0000	8016	0000	0000	Intel Corporation	Survise Point-CP PCI Express Rolt Port #7
@ 8086	9021	1043	1520	Intel Corporation	Survise Point-CP-PMC
Ø 1011	9010	0000	0000	Intel Corporation	Survise Point CP PCI Express Root Part #1
O 8086	9071	1043	1620	Intel Corporation.	Survise Point CP HD Audio
@ 1464	4343	1068	0021	Broadcam Inc	BCM4350 802.11ac Wireless Network Adapter
@ 8086	9073	1043	1520	Intel Corporation	Survise Point-LP Skillus
0 1015	9058	1043	1520	Intel Corporation	Survise Point-LP LPC Controller

Beitrag von "mt-fr" vom 29. September 2018, 19:46

turn off hd630 and only use gtx1050

and i have mac os 10.14 after use new kext i can see gtx in graphic tab! (i haven't nvidia web yet)

MR. in images i send 3 images for ---> how can i install

- Intel Gaussian Mixture Mode
- Apple Intel Thermal Subsystem
- Intel SMBus Controller

?

for fan ==> only control in windows can you use windows data to set fan in mac ?

Beitrag von "Noir0SX" vom 29. September 2018, 20:08

@anonymous writer Könnte das Testobjekt sein (Ambiente Light Sensor) 😌

Beitrag von "anonymous_writer" vom 29. September 2018, 20:40

Hi <u>@mt-fr</u>,

I like to help you and I have some ideas too. Today, it is already late in Germany and I worked on a wifi dw-1820a for my laptop which gave me a lot of work and stress.

Hi @NoirOSX,

Anscheinend bin ich immer noch der Einzige welcher einen funktionierenden Ambiente Light Sensor möchte.

Hilfreich ist da immer der Erfahrungsaustausch, wobei der für die DW-1820a eher Zufall war.

Beitrag von "mt-fr" vom 29. September 2018, 20:46

Edit by al6042 -> Do yourself a favor and do not quote post, which came directly before you replied...

This is considered as SPAM and will result in a forum ban...

ok . i love your work 🤎 and your ideas . i'm Waiting

Beitrag von "anonymous_writer" vom 3. Oktober 2018, 10:40

This two files should get work Apple Intel Thermal Subsystem and Intel SMBus Controller .

Intel Gaussian Mixture Mode > Does this device also exist for OSX and when yes which driver will be load?

If you can answer this question I can connect the device with the OSX device driver.

Fan > No Device ID, therefore unfortunately no possibility to integrate this in OSX. Sorry.

Beitrag von "mt-fr" vom 4. Oktober 2018, 20:03

Hi.

thank you .

"Intel Gaussian Mixture Model > Does this device also exist for OSX and when yes which driver will be load?"? i've searched about it but i can't find driver for that only for linux or windows . after used two file ---> my touchpad doesn't worked .

Beitrag von "anonymous_writer" vom 4. Oktober 2018, 21:46

Hi <u>@mt-fr</u>,

please delete files from post 95 and try instead these two files.

For Intel Gaussian Mixture Model I will write back later.

Beitrag von "mt-fr" vom 13. Oktober 2018, 19:44

https://github.com/Mohammadtag...jave-For-Asus-ROG-GL553VD

https://github.com/Mohammadtag...erra-For-Asus-ROG-GL553VD

Hi . i think project complete . thank a lot .

Beitrag von "anonymous_writer" vom 14. Oktober 2018, 15:06

Hi <u>mt-fr</u>

perfect done, thanks for providing yours EFI-Folder for the forum.

Beitrag von "adra" vom 18. Oktober 2018, 17:58

Hi mt-fr,

I followed your instructions to install trackpad on Mojave but it doesn't work for me.

I ran Kext Utility after deleting AppleIntelLpssI2C.kext and AppleIntelLpssI2CController.kext from System/Library/Extensions and rebooted with VoodooHDA.kext in EFI/Clover/Kexts/10.14/ folder and no result. Mac keeps booting without touchpad

Everything else is super. Intel HD630, HDMI, Audio, Bluetooth, Ethernet and Keyboard Fn keys are working like a charm! Thanks for all your work.