## **HP EliteDesk 800 G4 Mini BIOS Configuration**

Document Version 1.1 02-October-2020

## Security

- TPM Embedded Security
  - o TPM Device: Hidden
  - o TPM Activation Policy: No prompts
- BIOS Sure Start
  - All options unchecked
- Intel SGX: Disable

## Advanced

- Boot Options
  - Startup Delay: 5. (useful during testing to give time for Function key presses)
  - Fast Boot: unchecked
  - USB Storage Boot: checked
  - Network (PXE) Boot: unchecked
  - Audio Alerts During Boot: unchecked (to disable beep after pressing F9 at boot)
  - UEFI Boot Order
    - USB
    - Other boot drives as desired
  - Legacy Boot Order
    - Unchecked
- HP Sure Recover
  - Unchecked
- Secure Boot Configuration
  - Legacy Support Disable and Secure Boot Disable
  - Secure Boot Key Management
    - All options unchecked
- System Options
  - Configure Storage Controller for RAID: unchecked
  - Configure Storage Controller for Intel Optane: unchecked
  - Turbo-boost: checked
  - Hyperthreading: checked
  - Multi-processor: checked
  - Virtualization Technology (VTx): checked
  - Virtualization Technology for Directed I/O (VTd): unchecked
  - M.2 SSD 1: checked
  - o M.2 SSD 2: checked
  - M.2 WLAN BT (unchecked if you have Intel WLAN / BT device or don't have WLAN / BT)
  - Allow PCIe/PCI SERR# Interrupt: checked

- o Power Button Override: 4 sec
- USB Type-C Connector System Software Interface (USCI): unchecked
- o HP Application Driver: unchecked
- Built-In Device Options
  - Embedded LAN Controller: checked
  - Wake On LAN: DisabledDust Filter: Unchecked
  - Video Memory Size: 64MB 512MB
  - Audio Device: checkedMicrophone: Enable
  - o Internal Speakers: checked
  - Increase Idle Fan Speed (%): 0
  - M.2 USB / Bluetooth: Unchecked (disabled in System Options)
- Port Options
  - o Front USB Ports: checked
  - Front USB Port 1: checked
  - Front USB Port 2: checked
  - o Front USB Port 3: checked
  - o Rear USB Port 1: checked
  - Rear USB Port 2: checked
  - o Rear USB Port 3: checked
  - o Rear USB Port 4: checked
  - USB Legacy Port Charging: unchecked
  - o Front USB Type-C Downstream Charging: unchecked
  - SATA 0: checked
  - Restrict USB Devices: Allow all USB Devices
- Option ROM Launch Policy
  - This is grayed out for me (probably as a result of another selection)
- Power Management Options
  - Runtime Power Management: checked
  - Extended Idle Power States: checked
  - S5 Maximum Power Savings: checked
  - SATA Power Management: checked
  - PCI Express Power Management: checked
  - Power On from Keyboard Ports: this option is grayed out for me
  - Unique Sleep State Blink Rates: unchecked
- Remote Management Options
  - Intel Management Engine (ME): checked (required for proper UHD 630 Sleep / Wake)
  - o Intel Active Management Technology (AMT): unchecked