

**Erledigt**

## **Ozmosis can not load any files in the Oz directory**

**Beitrag von „xlazy.xyz“ vom 15. April 2017, 15:23**

[Zitat von griven](#)

Why Clover if you use OZ? Here is a patched DSDT with LayoutID set to LayoutID1: [DSDT.aml](#) place it on your EFI Partition under Efi/Oz/Acpi/Load also place AppleALC-OZM.kext taken from here [AppleALC - der dynamische AppleHDA Patcher - immer aktuell](#) and Lilu.kext taken from here: [Lilu - Generic kext patcher \(neue Grundlage für AppleALC 1.1.x und Shiki 2.x.x\)](#) into /Efi/Oz/Darwin/Extensions/Common/ and thats it sound should work afterwards.

Once, I used Clover.

I have placed the files on the right dir , and I place AppleIntelE1000e.kext on /efi/oz/darwin/extensions/common/ for a test. AppleIntelE1000e.kext can not load.

Now I will delete the Oz dir and then reflash the rom ,maybe it will work afterwards?