

Erledigt

Track Pad 2 Systemeinstellungen hängen sich auf

Beitrag von „griven“ vom 3. März 2018, 21:16

Der `shikigva`=steuert das Verhalten von shiki sprich er ermöglicht es shiki zu konfigurieren um bestimmte Dinge zu tun oder eben auch nicht zu tun. Die Einstellung zu der ich geraten hatte setzt sich wie folgt zusammen:

Code

1. `AllowNonBGRA = 2,`
2. `// Some GPU+CPU combinations are not meant to provide hardware acceleration and need to be patched.`
3. `// Fix hardware acceleration with NVIDIA+SKL, NVIDIA+KBL, AMD+IVB, NVIDIA+SNB.`

und

Code

1. `ForceCompatibleRenderer = 4,`
2. `// Unlike 10.12 and earlier, on 10.13 AppleGVA patches do not apply to all processes, and each`
3. `// process needs to be patched explicitly. This bit ensures that processes present in WHITELIST`
4. `// section of Patches.plist will definitely get the fixes even on 10.13.`
5. `// On 10.13 this must be used if any of the following bits are used:`
6. `// - ForceOnlineRenderer`
7. `// - AllowNonBGRA`
8. `// - ForceCompatibleRenderer`
9. `// - ReplaceBoardID`
10. `// - FixSandyBridgeClassName`

in Summe also 6. Gewählt habe ich so weil bei Dir der Fall NVIDIA+Skylake zutreffend ist.