

Erledigt

OZMOSIS REQUEST THREAD / Ozmosis Anfragen [1. Beitrag beachten!]

Beitrag von „xaviersilva28470“ vom 7. März 2018, 13:52

On the io shield plate it shows that is the usb at the bottom close to the hdmi port I did use both ports the usb port 2.0 and the 3.0 and I get the same result then I use an flashing utility called Aptio 4 AMI Firmware Update Utility, and in that utility there is a setting that is called force [bios update](#) and the same result shows that this is not a proper bios granted I was using a windows environment. i hope to find somebody that was able to flash that tipe of motherboard