

Erledigt

Does Oz understand Xeon CPU's and how to make it work?

Beitrag von „firefly_can_fly“ vom 11. Mai 2018, 13:41

griven - I flashed made by you Z97XUD3H_HighSierra_Unsolid.10b , it went partly good. From my previous experience, after a flash, I can hit "del" or "f12" and after go to bios setting or boot menu, but if after boot I won't hit some of this buttons - bios loading screen would freeze and the only reboot would help.

After flashing the bios I went to "del" and fixed settings chose my primary graphics to load - PCI 1 and saved the setting.

On new boot, I flushed nvram.

After reboot, no usual Oz spashscreen, only freeze.

Making reboot with button, hitting f12 afterward.

In the boot menu, I have clover if I check to boot directly to macros - black screen and even HDD activity led on system block not blinking.

I don't know much but seems that Oz, not even initiating.

After booting from clover there is OZ folder in EFI, but it's only folders.

So I gave a try to load kexts from clover and try with that - nothing, same black screen.

Took defaults you provided with roms, it's blank, but to understand whats wrong decision to go with verbose, but not verbose.

At this point, I don't know where to dig, because it seems that Oz just not loading.

This is Oz folder from EFI:

<https://fex.net/907379364537?fileId=467303880>

Maybe someone encountered something similar, or I'm just making it all wrong?