

Anleitung: High Sierra auf HP Elitebook 8460p mit Intel Core i7-2620M und ATI HD 6470M

Beitrag von „gamal“ vom 27. Oktober 2018, 22:11

Please help

HP Elitebook 8460p | Core i5 2520M | 4GB DDR3 RAM | 250GB SATA HDD | 250GB

AMD Radeon HD 6470M 1GB | OSX El-capitan

The problem in the definition of AMD Radeon HD 6470M is only 3M

And with the use of EFI files

After the boot appear a black screen

No data appears until "Load Video Bics" is disabled from the Clover boot screen

Almost everything works fine except for this problem

NOTE The same computer is fully functional on the Captain system

Please help

I am working on this problem a month ago