

Dell Vostro 5370

Beitrag von „tprimus“ vom 27. Juni 2019, 07:32

Hallo [Harper Lewis](#),

ich habe immer Problemen mit Schlaf...

Die habe ich jetzt gefunden:

Code

```
1. Time stamp          Domain          Message
   Duration          Delay
2. =====
   =====
3. UUID: CAD8959D-9D44-450F-BBB7-99B71F68E7B6
4. 2019-06-27 00:06:12 +0200 Notification      Display is turned off

5. 2019-06-27 00:06:12 +0200 Assertions          Kernel Idle sleep preventers: -None-
6. 2019-06-27 00:06:12 +0200 Assertions          PID 52(powerd) Created
   InternalPreventSleep      "com.apple.powermanagement.darkwakelinger"      00:00:00
   id:0x0xd00009291 [System: PrevIdle SRPrevSleep kCPU]
7. 2019-06-27 00:06:27 +0200 Assertions          PID 52(powerd) TimedOut
   InternalPreventSleep      "com.apple.powermanagement.darkwakelinger"      00:00:15
   id:0x0xd00009291 [System: SRPrevSleep kCPU]
8. 2019-06-27 00:06:27 +0200 Sleep                Entering Sleep state due to 'Clamshell
   Sleep':TCPKeepAlive=disabled Using Batt (Charge:84%) 4 secs
9. 2019-06-27 00:06:30 +0200 PM Client Acks        Delays to Sleep notifications:
   [com.apple.apsd is slow(2639 ms)]
10. 2019-06-27 00:06:30 +0200 Kernel Client Acks   Delays to Sleep notifications:
   [AppleIntelFramebuffer driver is slow(msg: SetState to 1)(1438 ms)]
11. 2019-06-27 00:06:30 +0200 Assertions          PID 163(mDNSResponder) Created
   MaintenanceWake      "mDNSResponder:maintenance"      00:00:00      id:0x0xd000092a7
   [System: PrevIdle]
12. 2019-06-27 00:06:30 +0200 Assertions          PID 163(mDNSResponder) Released
   MaintenanceWake      "mDNSResponder:maintenance"      00:00:00      id:0x0xd000092a7
   [System: PrevIdle]
13. 2019-06-27 00:06:30 +0200 Assertions          Kernel Idle sleep preventers:
   IODisplayWrangler
```

14. 2019-06-27 00:06:30 +0200 Notification Display is turned on
15. 2019-06-27 00:06:31 +0200 Wake Wake from Deep Idle [CDNVA] due to GLAN
XDCI/: Using BATT (Charge:84%) 31 secs
16. 2019-06-27 00:06:31 +0200 HibernateStats hibmode=0 standbydelay=10800
791
17. 2019-06-27 00:06:31 +0200 WakeTime WakeTime: 346.226 sec
18. 2019-06-27 00:06:31 +0200 Kernel Client Acks Delays to Wake notifications:
[ApplePS2Controller driver is slow(msg: SetState to 2)(363 ms)] [AppleIntelFramebuffer
driver is slow(msg: SetState to 2)(364 ms)] [AppleHDADriver driver is slow(msg: SetState
to 1)(501 ms)]
- 19.
20. Sleep/Wakes since boot at 2019-06-26 13:01:06 +0200 :511 Dark Wake Count in this
sleep cycle:0

Alles anzeigen

Ein Möglichkeit wäre:

tony.....com/threads/instant-wake-from-sleep-wake-reason-glan-xdci-skylake-el-capitan.198588/

1. Find "Device (GLAN)", you should see sth like this:

Code

1. Device (GLAN)
2. { //..... Method (_PRW, 0, NotSerialized) // _PRW: Power Resources for Wake { Return
(GPRW (0x0D, 0x04)) } //.....
3. }

2. Change "Return (GPRW (0x0D, 0x04))" to "Return (GPRW (0x09, 0x04))"
or remove entire _PRW block

Könntest du dadrin mir helfen oder ein patch schicken? Ich hatte noch nie Glück damit. Ich bekomme immer Fehlermeldungen wenn ich mit maciASL compile-en probiere...

Danke im voraus!