

## Erledigt **OpenCore ALC221 kein sound**

**Beitrag von „ochja“ vom 23. April 2020, 23:17**

ok - nochmal was an der Config geändert ... jetzt habe ich Sound über Displayport (RX580)



ich habe mal das Debug AppleHDA kext installiert und mit -alcdebug gestartet

nochmal neues log

Code

1. 020-04-23 23:20:11.718426+0200 localhost kernel[0]: calling mpo\_policy\_init for Lilu
2. 2020-04-23 23:20:11.718428+0200 localhost kernel[0]: Security policy loaded: Lilu Kernel Extension 1.4.3 (Lilu)
3. 2020-04-23 23:20:11.718679+0200 localhost kernel[0]: (Lilu) AppleALC init: @ (DBG) AppleALC bootstrap DBG-148-2020-04-06
4. 2020-04-23 23:20:12.170446+0200 localhost kernel[0]: (Lilu) Lilu rtc: @ rtc read failure 1 bytes from 180 E00002C2
5. 2020-04-23 23:20:25.482976+0200 localhost kernel[0]: (Lilu) AppleALC iokit: @ (DBG) getOSData vendor-id has 8086 value
6. 2020-04-23 23:20:25.482979+0200 localhost kernel[0]: (Lilu) AppleALC iokit: @ (DBG) getOSData device-id has 8D20 value
7. 2020-04-23 23:20:25.482982+0200 localhost kernel[0]: (Lilu) AppleALC iokit: @ (DBG) getOSData revision-id has 5 value

8. 2020-04-23 23:20:25.482984+0200 localhost kernel[0]: (Lilu) AppleALC iokit: @ (DBG) getOSData alc-layout-id has B value
9. 2020-04-23 23:20:25.482989+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) found 2 audio controllers
10. 2020-04-23 23:20:25.482992+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) validating 0 controller 1002:AAF0:0
11. 2020-04-23 23:20:25.482994+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 0 mod 1002:AAC8
12. 2020-04-23 23:20:25.482996+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 1 mod 1002:AAE8
13. 2020-04-23 23:20:25.482999+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 2 mod 1002:AB08
14. 2020-04-23 23:20:25.483001+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 3 mod 1022:1457
15. 2020-04-23 23:20:25.483003+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 4 mod 1022:1487
16. 2020-04-23 23:20:25.483010+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 5 mod 1022:15E3
17. 2020-04-23 23:20:25.483013+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 6 mod 8086:C0C
18. 2020-04-23 23:20:25.483015+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 7 mod 8086:F04
19. 2020-04-23 23:20:25.483017+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 8 mod 8086:8CA0
20. 2020-04-23 23:20:25.483019+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 9 mod 8086:8D20
21. 2020-04-23 23:20:25.483021+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 10 mod 8086:8D21
22. 2020-04-23 23:20:25.483024+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 11 mod 8086:9DC8
23. 2020-04-23 23:20:25.483026+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 12 mod 8086:A171
24. 2020-04-23 23:20:25.483028+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 13 mod 8086:A2F0
25. 2020-04-23 23:20:25.483030+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 14 mod 8086:A1F0
26. 2020-04-23 23:20:25.483032+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 15 mod 8086:A348
27. 2020-04-23 23:20:25.483034+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 16 mod 10DE:E0F
28. 2020-04-23 23:20:25.483037+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 17 mod 10DE:FB0

29. 2020-04-23 23:20:25.483039+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 18 mod 10DE:FB8
30. 2020-04-23 23:20:25.483041+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 19 mod 10DE:FB9
31. 2020-04-23 23:20:25.483043+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 20 mod 10DE:FBA
32. 2020-04-23 23:20:25.483045+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 21 mod 10DE:FBB
33. 2020-04-23 23:20:25.483047+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 22 mod 10DE:FBC
34. 2020-04-23 23:20:25.483049+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 23 mod 10DE:10EF
35. 2020-04-23 23:20:25.483051+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 24 mod 10DE:10F0
36. 2020-04-23 23:20:25.483053+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 25 mod 10DE:10F1
37. 2020-04-23 23:20:25.483055+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 26 mod 8086:2C8
38. 2020-04-23 23:20:25.483058+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) validating 1 controller 8086:8D20:5
39. 2020-04-23 23:20:25.483060+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 0 mod 1002:AAC8
40. 2020-04-23 23:20:25.483062+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 1 mod 1002:AAE8
41. 2020-04-23 23:20:25.483064+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 2 mod 1002:AB08
42. 2020-04-23 23:20:25.483066+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 3 mod 1022:1457
43. 2020-04-23 23:20:25.483068+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 4 mod 1022:1487
44. 2020-04-23 23:20:25.483070+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 5 mod 1022:15E3
45. 2020-04-23 23:20:25.483072+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 6 mod 8086:C0C
46. 2020-04-23 23:20:25.483074+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 7 mod 8086:F04
47. 2020-04-23 23:20:25.483076+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 8 mod 8086:8CA0
48. 2020-04-23 23:20:25.483078+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) comparing to 9 mod 8086:8D20
49. 2020-04-23 23:20:25.483080+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) found mod for 1 controller

50. 2020-04-23 23:20:25.483083+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) missing ControllerModInfo for 0 controller
51. 2020-04-23 23:20:25.483085+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) handling 1 controller 8086:8D20 with 4 patches
52. 2020-04-23 23:20:25.483555+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) missing ControllerModInfo for 0 controller
53. 2020-04-23 23:20:25.483558+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) handling 1 controller 8086:8D20 with 4 patches
54. 2020-04-23 23:20:25.483561+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) checking patch 0 for 1 kext (com.apple.driver.AppleHDAController)
55. 2020-04-23 23:20:25.483565+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) applying patch 0 for 1 kext (com.apple.driver.AppleHDAController)
56. 2020-04-23 23:20:25.483719+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) checking patch 1 for 1 kext (com.apple.driver.AppleHDAController)
57. 2020-04-23 23:20:25.483722+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) applying patch 1 for 1 kext (com.apple.driver.AppleHDAController)
58. 2020-04-23 23:20:25.483921+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) checking patch 2 for 1 kext (com.apple.driver.AppleHDAController)
59. 2020-04-23 23:20:25.483924+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) applying patch 2 for 1 kext (com.apple.driver.AppleHDAController)
60. 2020-04-23 23:20:25.484074+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) checking patch 3 for 1 kext (com.apple.driver.AppleHDAController)
61. 2020-04-23 23:20:25.484077+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) applying patch 3 for 1 kext (com.apple.driver.AppleHDAController)
62. 2020-04-23 23:20:25.484395+0200 localhost kernel[0]: (Lilu) AppleALC alc: @ (DBG) AppleGFXHDA probe for HDAU
63. 2020-04-23 23:20:25.485175+0200 localhost kernel[0]: (Lilu) AppleALC iokit: @ (DBG) getOSData alc-delay was not found

Alles anzeigen

hier mal die derzeitigen Einträge in der config.plist

