

Gigabyte Z390 DESIGNARE: OpenCore-EFI-Ordner und Anleitung

Beitrag von „JimSalabim“ vom 26. Mai 2020, 16:40

[teomi62](#) So you mean the correct boot disk is not selected automatically any longer (but you can choose it manually) and choosing the correct disk in System Preferences does not result in automatic boot of the correct disk?

If so: resetting NVRAM could help, because the default boot disk is stored there. Afterwards make sure that the OpenCore disk is selected as first option in Boot Option Priorities in BIOS and try again setting the correct disk as default in System Preferences.