

OSX Catalina - Realtek ALC274 kein Sound

Beitrag von „prayer“ vom 1. Januar 2021, 20:11

Hallo, anbei der Screenshot

Hackintool v3.4.9

System

Patch

Boot

NVRAM

Extensions

Displays

Sound

USB

Disks

PCIe

Power

Calc

Utilities

Logs

Sound

	Device	Sub Device	Codec	Revision	Name
	0x80869D71	0x17AA36DC	0x10EC0274	0x0000	ALC274

Pin Configuration

	NID	PinDefault		Device	Connector	Port	Grp
☒	18 (0x12)	90A00130	In	Mic In	Unknown	Fixed	Int
☒	22 (0x16)	90170110	Out	Speaker	Other Analog	Fixed	Int
☒	25 (0x19)	04810040	In	Line In	1/8" Stereo/Mono	Jack	Ext

Audio Info

Name	Wert
Class	AppleHDA Driver
Hersteller	Intel Corporation (0x8086)
Device	Sunrise Point-LP HD Audio (0x9D71)* * You may require Spoof Audio Device ID
Sub Vendor	Lenovo (0x17AA)
Sub Device	??? (0x36DC)
Codec Vendor	Realtek (0x10EC)
Codec Name	ALC274 (0x0274)
ALC Layout ID	21
Revision	0x100004
Min. Kernel	13
Max. Kernel	15
AFG Low Power State	<03000000>
Codec ID	0x10EC0274
Config Data	<01670c02 02170c02>
Func Group	1
Codec	Andres ZeroCross - Realtek ALC274 for Dell Inspiron 27-7...
Wake Verb Reinit	Yes
Layout ID	7

HEADSOFT

Tip me!

<https://www.hackintosh-forum.de/forum/thread/52115-osx-catalina-realtek-alc274-kein-sound/?postID=667711#post667711>

3