

Dell XPS13-9350 camera problem

Beitrag von „chronicie“ vom 8. Januar 2021, 13:35

FaceTime's camera works only the first time it's turned on, and no images when it's turned on again.

SystemLog:

```
Jan 7 11:28:34 ChenKais-MacBook-Pro com.apple.xpc.launchd[1] (com.apple.xpc.launchd.domain.user.501): Service
"application.com.apple.FaceTime.1152921500311898998.1152921500311899003" tried to register for endpoint
"com.apple.madrid-idswake" already registered by owner: com.apple.imagent
```

Bundle	com.apple.iokit.IUSBSFamily	Property	Type	Value
↳ Root		sessionID	Number	0x9c3855a1
↳ IODeviceFamily		USBSpeed	Number	0x1
↳ AppleUSBCFamilyExpert		IOServiceNameMatching	Number	0x00000037
↳ IOUSB		IOProduct	Number	0x470c
↳ AppleCNPPIO		Manufacturer	Number	0x1
↳ IOACPI		ModelNameClass	Number	0x01
↳ IOACPI4000000		IOPowerManagement	Dictionary	7 values
↳ IOACPI4000000		IODevice	Number	0x0029
↳ Integrated_Webcam_JD014500000		ManufacturerClass	Number	0x45
↳ Integrated_Webcam00		IOProduct	Number	0x1
↳ Integrated_Webcam01		SerialNumber	Number	0x00
↳ IOResources		ManufacturerConfigurations	Number	0x1
↳ AppleIOUSBResources		USB_ProductName	String	Integrated_Webcam_JD
↳ AppleIOUSBLegacyIOKit		USB_Address	Number	0x1
↳ AppleIOUSB4000000		LocationID	Number	0x14500000
↳ Integrated_Webcam_JD014500000		IODeviceNameClass	Number	0x1
↳ Integrated_Webcam00		IOUSB	Number	0x001
↳ Integrated_Webcam01		Built-In	Boolean	True
		non-volatile	String	yes
		IOCFPlugInTypes	Dictionary	1 value
		IOUSBCurrentConfiguration	Number	0x1
		IOServicePlatform	Number	0x1
		USBPortType	Number	0x1
		IOServiceDEXITentiments	Array	1 value
		USB_VendorName	String	CH907F7M24876N8B01Z201
		Device Speed	Number	0x1
		Vendor	Number	0x45
		IOUSBProductString	String	Integrated_Webcam_JD
		IOServiceInterest	String	IOCommand is not serializable
		IOUSBAddress	Number	0x1
		IOUSBVendorString	String	CH907F7M24876N8B01Z201
		IOServiceNameOverride	String	IOUSBDevice