

Thunderbolt 3 HP ZBOOK G3 Problems

Beitrag von „EdD1024“ vom 11. Mai 2021, 09:15

Actually in most cases Thunderbolt does not work properly on any hackintosh laptop. Hotplug practically never. I've seen different older Dell XPS Laptops with minor success, but their owners invested weeks or months getting it to work.

For starters you might probably get best results if you connect everything before switching your laptop on, while disabling all security in the BIOS - if any options are available. Then what's connected through the BIOS might work to some extent or even normally.

Other than that it's hard to find a way forward.