

Ryzen 5 5600x und RX 6900 xt

Beitrag von „fabiosun“ vom 1. August 2022, 12:22



this is first bios you can use with your CPU

But, if your problem is similar to the one MSI X570 users have had in the past was not possible to solve it

Only users with 3xxx CPU series could solve (not all users) using first release of their motherboard bios

You are first user with different manufacturer and chipset than MSI I read to have this problem

Problem seems to be related that in latest osx some motherboard loose PCH support for NVME slot and sata

Some users solved this problem detaching all sata disks and using only nvme slot maintained from CPU (and not PCH)

but is weird that also as rock is affected by this problem user updated his signature