


Ryzentosh - Auros B550i PRO AX - "3,6GHz Unbekannt" fix ?

Beitrag von „fabiosun“ vom 8. August 2022, 13:31

[user1](#)



this is wrong

put there 0 or 3841

then you can delete also:

revcpu	Number	0 1
revcpuname	String	AMD Ryzen 5 3600

if you did all well cpu is seen well only with restrictevents

I would also suggest to enable Nvram Reset button and reset your NVRAM after this modifies