

Sequoia on Intel HD Graphics 530 - Image tearing when scrolling

Beitrag von „Telendos“ vom 29. Dezember 2025, 15:45

Hello, I have successfully installed MacOS Seequoia on a GIGABYTE GA-B150N PC with an Intel HD Graphics 530 graphics card. Sound, Internet, graphics with 1536MB work.

The problem is when scrolling the Internet, the image is torn and only the two front USB 2 work.

I am attaching my EFI and please help me how to fix the tearing of graphics and USB. Thank

you for your help

