

Sequoia on Intel HD Graphics 530 - Image tearing when scrolling

Beitrag von „Telendos“ vom 29. Dezember 2025, 15:45

Hello, I have successfully installed MacOS Seequoia on a GIGABYTE GA-B150N PC with an Intel HD Graphics 530 graphics card. Sound, Internet, graphics with 1536MB work.

The problem is when scrolling the Internet, the image is torn and only the two front USB 2 work.

I am attaching my EFI and please help me how to fix the tearing of graphics and USB. Thank

you for your help



Beitrag von „ralf.“ vom 31. Dezember 2025, 12:03

efis for i5 HD530

Beitrag von „Telendos“ vom 1. Januar 2026, 10:26

[Zitat von ralf.](#)

efis for i5 HD530

ralf.,

thanks for the help, USB is working now, I modified EFI for HD530. Graphics, sound, internet, USB are working. When scrolling the mouse, the image still sometimes jerks. If anyone has any other ideas for modifying EFI, I would be happy if they could help.